CARE INSTRUCTION FOR WIRE BASKET TOP - SMOKED OAK

Apply linseed oil 4 times the first month and afterwards from time to time.

It will close the surface and make the top more sturdy.

Alternatively, use beeswax to treat and protect the smoked oak veneer.

Never wipe with a damp cloth.

SMOKED OAK

Smoked oak can only be produced because oak contains the active substance tannin by nature. The natural tannin content is determined by numerous factors such as climate during the growth phase and by soil conditions.

The natural tannin content reacts with ammonia during the smoking process and darkens the oak. The degree of discolouration therefore depends on the oak's natural tannin content on the one hand and on the duration of the smoking process on the other. The colour variation of the smoked oak is therefore an authentic characteristic.

WWW.FERMLIVING.COM



CARE INSTRUCTIONS WIRE BASKET TOP OILED OAK

Apply linseed oil 4 times the first month and afterwards from time to time.

It will close the surface and make the top more sturdy.

Alternatively, use beeswax to treat and protect the oiled oak veneer.

Do not wipe with a wet cloth.

WWW.FERMLIVING.COM



CARE INSTRUCTIONS WIRE BASKET TOP - BLACK OAK

The black stained oak has an acrylic coating. We recommend cleaning
with a dry cloth and from time to time a damp cloth can be used.
Do not treat with wax or other liquids for wood.

WWW.FERMLIVING.COM

